



Fig. 1





F i g. 4





Fig. 5



6/17
Fig. 6






Fig. 7




8/17

Fig. 9




0961365-00001

F i g. 10




10/17

Fig. 11




09961365.002501

Fig. 12a



TORSION COIL SPRING ALONE

Fig. 12b



TORSION COIL SPRING + BUSHING

[illegible]

12/17
Fig. 13





Fig. 14



13/17

Fig. 15




Fig. 16





Fig. 17



15/17

Fig. 18




Fig. 19





Fig. 20



17/17

Fig. 21

WATER SPRAYING TEST RESULTS

